

**Flood Control Project Maintenance
Levee Inspections****LMA District Cover Sheet****Spring 2011 Levee Inspection Results****Tehama County Flood Control and Water Conservation District**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Tehama County Flood Control and Water Conservation District

Waterway			Bank	Unit Miles
Unit No. 01 Deer Creek			Left	4.11

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/8/2011 - 3/8/2011			
DWR Inspector	Bob Duffey			
Accompanied By	Brandon Konicke Tehame Co.			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Deer Creek						Left	4.11	03/08/2011 03/08/2011	Bob Duffey	
LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	2.04	2.23	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	39.968387 ° -122.016387 °	39.966968 ° -122.019372 °	2 Y
2	2.50	2.58	Earthen Levee	Slope Stability	CR	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	39.967016 ° -122.024068 °	39.966455 ° -122.025531 °	7
3	2.72	2.76	Earthen Levee	Slope Stability	CR	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	39.965434 ° -122.027776 °	39.965180 ° -122.028331 °	8 Y
4	2.79	2.79	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	39.964773 ° -122.029060 °	39.964773 ° -122.029060 °	915 Y
5	2.84	2.84	Earthen Levee	Encroachments	WS	C	Tree or limb	39.964387 ° -122.029733 °	39.964387 ° -122.029733 °	914
6	2.85	2.85	Earthen Levee	Encroachments	LS	C	Tree or limb	39.964293 ° -122.029725 °	39.964293 ° -122.029725 °	3
7	2.98	3.00	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2009: 10 ft berm, 2:1 slope, tree hazards, sands and cobbles, 3 ft/s [2009 SiteID:DRC_2-4_L]	39.962911 ° -122.031419 °	39.962725 ° -122.031669 °	1
8	3.64	3.64	Earthen Levee	Encroachments	CR	PO	Fences	39.945249 ° -122.053720 °	39.945249 ° -122.053720 °	9 Y
9	3.74	3.74	Earthen Levee	Encroachments	CR	PO	Fences	39.944432 ° -122.054029 °	39.944432 ° -122.054029 °	10 Y
10	3.79	3.79	Earthen Levee	Encroachments	LS	M	Prunings	39.944135 ° -122.054788 °	39.944135 ° -122.054788 °	5
11	3.99	3.99	Earthen Levee	Encroachments	LS	C	Prunings	39.941922 ° -122.057228 °	39.941910 ° -122.057238 °	6

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.11	03/08/2011 03/08/2011	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	2.04
End Levee Mile	2.23
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove agricultural ditch from toe of levee.	
rduffey_s_20110404_238.jpg	



Levee Mile Report Line	3
Start Levee Mile	2.72
End Levee Mile	2.76
Location	Crown
Category	Earthen Levee
Item	Slope Stability
Erosion on crown and both slopes.	
rduffey_s_20110228_071.jpg	



Levee Mile Report Line	4
Start Levee Mile	2.79
End Levee Mile	2.79
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving
Erosion along the channel.	
rduffey_s_20110228_074.jpg	

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011


Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.11	03/08/2011 03/08/2011	Bob Duffey

Levee Mile Report Line	8
Start Levee Mile	3.64
End Levee Mile	3.64
Location	Crown
Category	Earthen Levee
Item	Encroachments

View of the non-permitted gate on the crown of the levee.

rduffey_s_20110228_072.jpg



Levee Mile Report Line	9
Start Levee Mile	3.74
End Levee Mile	3.74
Location	Crown
Category	Earthen Levee
Item	Encroachments

View of the non-permitted gate on the crown roadway.

rduffey_s_20110228_073.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Tehama County Flood Control and Water Conservation District

Waterway			Bank	Unit Miles
Unit No. 02 Deer Creek			Right	1.50
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/8/2011 - 3/8/2011			
DWR Inspector	Bob Duffey			
Accompanied By	Brandon Konicke Tehama Co.			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Deer Creek							Right	1.50	03/08/2011 03/08/2011	Bob Duffey

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.31	0.31	Earthen Levee	Encroachments	LS	M	Debris	39.970305 ° -122.014465 °	39.970305 ° -122.014465 °	2 Y
2	0.36	0.36	Earthen Levee	Encroachments	LS	PO	Buildings	39.970117 ° -122.015365 °	39.970117 ° -122.015365 °	7 Y
3	0.86	0.91	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2009: 10 ft berm, vertical slope, tree hazards and holes, sands and cobbles, 5 ft/s [2009 SiteID:DRC_0-9_R]	39.968164 ° -122.023828 °	39.967767 ° -122.024619 °	1
4	1.30	1.30	Earthen Levee	Encroachments	WS	M	Firewood	39.964883 ° -122.030655 °	39.964883 ° -122.030655 °	6 Y

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Deer Creek	Right	1.50	03/08/2011 03/08/2011	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.31
End Levee Mile	0.31
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of debris & wire at toe of levee.

rduffey_s_20110228_075.jpg



Levee Mile Report Line	2
Start Levee Mile	0.36
End Levee Mile	0.36
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of building at toe of levee.

rduffey_s_20110228_076.jpg



Levee Mile Report Line	4
Start Levee Mile	1.30
End Levee Mile	1.30
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Remove all fire wood.

rduffey_s_20110404_237.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Tehama County Flood Control and Water Conservation District

Waterway			Bank	Unit Miles
Unit No. 04 Elder Creek			Left	4.07
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/8/2011 - 3/8/2011			
DWR Inspector	Bob Duffey			
Accompanied By	Brandon Konicke Tehama Co.			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 Elder Creek						Left	4.07	03/08/2011 03/08/2011	Bob Duffey	
LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	1.60	1.71	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.052607 ° -122.161418 °	40.053558 ° -122.159903 °	3 Y
2	2.00	2.22	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	40.052610 ° -122.154793 °	40.051990 ° -122.150867 °	8 Y
3	2.53	2.53	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.052872 ° -122.145495 °	40.052872 ° -122.145495 °	2
4	2.66	2.66	Earthen Levee	Encroachments	LS	M	Debris	40.054352 ° -122.144245 °	40.054352 ° -122.144245 °	4
5	2.82	2.85	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.055033 ° -122.141457 °	40.055595 ° -122.141203 °	916
6	2.84	2.84	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	40.055584 ° -122.141332 °	40.055584 ° -122.141332 °	19
7	3.02	3.02	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	40.056514 ° -122.139449 °	40.056514 ° -122.139449 °	5
8	3.03	3.03	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	40.056388 ° -122.139168 °	40.056388 ° -122.139168 °	10
9	3.15	3.15	Earthen Levee	Encroachments	LS	M	Stairways	40.057285 ° -122.137732 °	40.057285 ° -122.137732 °	1 Y
10	3.34	3.34	Earthen Levee	Encroachments	LS	M	Garbage	40.057558 ° -122.134417 °	40.057558 ° -122.134417 °	6 Y
11	3.72	3.77	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	40.055920 ° -122.128948 °	40.055945 ° -122.128310 °	7

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	4.07	03/08/2011 03/08/2011	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	1.60
End Levee Mile	1.71
Location	Water Side
Category	Earthen Levee
Item	Slope Stability

View of vehicle erosion on the crown & both slopes.

rduffey_s_20110228_078.jpg



Levee Mile Report Line	2
Start Levee Mile	2.00
End Levee Mile	2.22
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting

View of the crown roadway that needs gravel & grading.

rduffey_s_20110404_236.jpg



Levee Mile Report Line	9
Start Levee Mile	3.15
End Levee Mile	3.15
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the concrete stairways on the slope.

rduffey_s_20110228_077.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	4.07	03/08/2011 03/08/2011	Bob Duffey

Levee Mile Report Line	10
Start Levee Mile	3.34
End Levee Mile	3.34
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the garbage and metal at the toe of the levee & along the slope of the landside.

rduffey_s_20110228_079.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Tehama County Flood Control and Water Conservation District

Waterway				Bank	Unit Miles
Unit No. 05 Elder Creek				Right	3.96
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	3/8/2011 - 3/8/2011				
DWR Inspector	Bob Duffey				
Accompanied By	Brandon Konicke Tehama Co.				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 05 Elder Creek						Right	3.96	03/08/2011 03/08/2011	Bob Duffey	
LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.81	0.81	Earthen Levee	Encroachments	LS	M	Prunings	40.050683 ° -122.177573 °	40.050683 ° -122.177573 °	1 Y
2	0.96	0.96	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	40.051425 ° -122.175218 °	40.051425 ° -122.175218 °	4
3	2.57	2.57	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	40.051675 ° -122.148122 °	40.051675 ° -122.148122 °	8 Y
4	2.70	2.76	Earthen Levee	Encroachments	LS	PO	Landscaping	40.051778 ° -122.145745 °	40.052243 ° -122.144825 °	2 Y
5	2.97	3.07	Earthen Levee	Encroachments	WS	C	Prunings	40.054162 ° -122.142298 °	40.054725 ° -122.140552 °	3
6	3.13	3.13	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	40.055632 ° -122.138910 °	40.055607 ° -122.138868 °	11
7	3.37	3.84	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	40.056831 ° -122.136365 °	40.054862 ° -122.129279 °	9
8	3.45	3.45	Earthen Levee	Erosion / Bank Caving	LS	M	Schedule repair of erosion site prior to the next inspection.	40.056727 ° -122.134888 °	40.056727 ° -122.134888 °	7
9	3.77	3.91	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	40.056922 ° -122.136365 °	40.054562 ° -122.128345 °	10

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.96	03/08/2011 03/08/2011	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.81
End Levee Mile	0.81
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the debris & pruning pile brush next to the toe.

rduffey_s_20110404_235.jpg



Levee Mile Report Line	3
Start Levee Mile	2.57
End Levee Mile	2.57
Location	Land Side
Category	Earthen Levee
Item	Animal Control

View of the bait station next to the squirrel holes on the landside slope.

rduffey_s_20110228_082.jpg



Levee Mile Report Line	4
Start Levee Mile	2.70
End Levee Mile	2.76
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the landscape along the slope.

rduffey_s_20110228_081.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor